



**1 SOUTH BUILDING 2ND FLOOR**  
 S3.3 SCALE: 1/8" = 1'-0"

**PLAN NOTES**

- N-1** FOR GENERAL STRUCTURAL NOTES SEE DRAWING S1.0 AND S1.1.
- N-2** REMOVE AND REPLACE CONCRETE WALKWAY, RAILING AND COLUMNS. 2ND FLOOR COLUMNS TO BE LOCATED DIRECTLY ABOVE 1ST FLOOR COLUMNS, REFERENCE 1/S3.2.
- N-3** REMOVE TIMBER FRAMED BALCONY AND REPLACE WITH CONCRETE BALCONY. REMOVE AND REPLACE RAILING.
- N-4** GUARDRAIL SYSTEM AND DECK COATING MUST ACCOMMODATE 1" EXPANSION JOINT.
- N-5** REMOVE AND REPLACE CONCRETE RADIAL STAIRS. SEE S4.5 AND S4.6 FOR NEW CONCRETE STAIR PLAN AND DETAILS.

**LEGEND**

- # INDICATES DOOR OR WINDOW TO BE REMOVED AND REPLACED. SEE SHEETS S1.1 AND S1.2 FOR WINDOW AND DOOR SCHEDULE.
- N-X INDICATES A PLAN NOTE

REVISIONS	
NO.	DATE

**RENOVATION/RESTORATION PROJECT**  
**MARINER BEACH CLUB**  
 4220 GULF BOULEVARD  
 ST. PETERSBURG BEACH, FLORIDA 33706

**billerreinhardt**  
 STRUCTURAL GROUP, INC.  
 4014 gulf highway suite 248, tampa, florida 33618  
 telephone : 813.908.7203 fax : 813.908.7303  
 email : info@billerreinhardt.com  
 State of Florida Certificate of Authorization No. 9149

FOR THE BEST OF SERVICE, PLEASE CONSULT THE PLANS AND SPECIFICATIONS CAREFULLY WITH THE APPLICABLE FEDERAL AND BUILDING CODES.

MICHAEL H. BILLER  
 FL. P.E. NO. 49972

**SOUTH BUILDING 2ND FLOOR**  
 DATE: 2-23-09 DRAWN BY: RC  
 JOB NO: 08-132 DESIGN BY: MB/CP/LL

SHEET NO.  
**S3.3**